

OUT58788

P 132320Z
 FM NPIC WASHDC
 TO RUCSC/SAC OFFUTT AFB OMAHA NEB
 RUCVAA/4080 STRAT WG OL 19 BARKSDALE AFB LA
 RUCVAA/2D RTS BARKSDALE AFB LA
 RUEKDA/DIA WASHDC
 RUECYH/NAVRECONTECHSUPPCEN SUITLAND MD
 RUEPIA/CIA WASHDC
 RUWBKN/15TH AF MARCH AFB RIVERSIDE CALIF
 RUWGAA/2 AF BARKSDALE AFB LA
 BT
 S E C R E T CITE NPIC 7454.

1966 JUN 13 23 33Z

15TH AF (FOR DI), SAC (FOR DIM/GOLDEN TREE/DOCR, DM 4) 2D AF (FOR DI).

1. CAMERA B-125 WAS USED IN MISSION 8100 FLOWN ON 11 JUNE 1966.

PROCESSING WAS ACCOMPLISHED BY BARKSDALE.

14 JUN 1966

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: SLIGHT INBOARD AND OUTBOARD ROLLER CHATTER IS PRESENT INTERMITTENTLY THROUGHOUT THE MISSION. A MANUFACTURER'S SPLICE IS LOCATED IN FRAME 0095.

C. 9L SIDE: A BAND OF FOG, PERPENDICULAR TO THE MAJOR AXIS, IS PRESENT ON FRAME 0000. THE MAJORITY OF THE POSITION INDICATOR LAMPS, NEAR THE DATA CHAMBER, ARE FAINT AND AT TIMES BARELY DETECTABLE. THE VERTICAL DOT POSITION INDICATOR LAMPS ARE BLOOMED. MINUTE HAIR LIKE OBSTRUCTIONS ARE INSIDE EACH FIDUCIAL. ULTRA-SONIC SPLICES WERE USED ON THE HEAD AND TAIL IDENTIS AND ALSO BETWEEN FRAMES 1198/1199 AND 1508/1509. ASSOCIATED WITH THE SPLICES MADE ON FRAMES 299 AND 1509 ARE CREASES AND WRINKLES IN THE FILM, DUE TO MISALIGNMENT OF THE FILM DURING THE SPLICING PROCEDURE. STATIC TRACES OF FOG ARE PRESENT ON BOTH FILM EDGES THROUGHOUT THE MISSION.

| Cy No. | Office |
|--------|---------|
| ✓ | ADMIN |
| ✓ | SEC BR |
| | P & DS |
| | CSD |
| | IPD |
| | PD |
| | PSD |
| | PSD-ICB |
| 345 | TID |
| | IAD |
| | PAG |
| | DIAXX-4 |
| | SPAD |
| | NSA-LO |
| | DIA-AP |

Advance copy
 Sanitized

SECRET

-2-

D. BOTH SIDES: THE FRAMES ARE CONSECUTIVELY TITLED 0000
THROUGH 1919.

E. THERE WERE NO MAJOR PROCESSING OR CAMERA MALFUNCTIONS.

3. POSITIVE:

A. PI SUITABILITY IS GOOD.

B. PRINTING AND PROCESSING WERE GOOD.

C. CLOUDS AND HAZE DEGRADE APPROXIMATELY 40 PERCENT OF THE
MISSION.

GP-1

S E C R E T

--END OF MESSAGE--